


CORNER RECORD

Document Number 3527-34-99

City of MAMMOTH LAKES

County of MONO, California

Brief Legal Description CENTERLINE MONUMENT, MAMMOTH VISTA NO. 3, S34, T3S, R.27E MDE & M



CORNER TYPE

Government Corner ☐ Control ☐
 Meander ☐ Property ☐
 Rancho ☐ Other ☒
 Date of Survey 8-13-98

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

END 2" IRON PIPE PER MB 9/33 @ THE POINT OF REVERSE CURVE EAST OF LOT 2, TIED OUT

A description of the physical condition of the monument as found and as set or reset: SET 2" PK WASHER
"4587" AS A DIRECT REPLACEMENT OF 2" IRON PIPE END PER MB 9/33 @ THE
POINT OF REVERSE CURVE EAST OF LOT 2. DESTROYED DURING ROAD CONSTRUCTION.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 1-21-99

Signed [Signature] L.S. or R.C.E. Number 4587



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1-25 1999 and examined and filed 1-29 1999.

Signed John K Beck Title DEPUTY MONO COUNTY SURVEYOR
LIC. EXP. 6-30-00




County Surveyor's Comment _____



NO SCALE

(R) Record Data Per MB 9/33

DIRECT REPLACED FND 2" IP
RCE 15160 PER MB 9/33 DESTROYED
DURING ROAD CONSTRUCTION
WITH 2" PK + WASHER "LS4587"



9/33

JV 1260